



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3914-041
Job Sheet 188197



Part No: D3914-041

Job Qty: 1 pcs

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 1/4/19

Job Tracking No:

Due Date: 3/4/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier	Sign-off
					Setup Hrs	Run Hrs		
100	Large Fab - Basket - 1	1 pcs	3/4/19		0.00	6.67	Large Fab - 1	
							Large Fab - 10	
							Large Fab - 2	
							Large Fab - 3	
							Large Fab - 4	
							Large Fab - 5	
							Large Fab - 6	
							Large Fab - 7	
							Large Fab - 8	JLA CC
							Large Fab - 9	
110	QC 9	1 pcs	3/4/19		0.00	0.00	QC 9 - 10	
							QC 9 - 18	
							QC 9 - 24	
							QC 9 - 43	DAS
							QC 9 - 50	43
							QC 9 - 9	9-89
120	QC 5	1 pcs	3/4/19		0.00	0.00	QC 5 - 10	
							QC 5 - 12	
							QC 5 - 17	
							QC 5 - 18	
							QC 5 - 19	
							QC 5 - 22	
							QC 5 - 24	
							QC 5 - 3	
							QC 5 - 38	
							QC 5 - 42	
							QC 5 - 43	DAS
							QC 5 - 49	43
							QC 5 - 51	9-89
							QC 5 - 58	

Plex 2/5/19 9:48 AM Dart.Hadley.Shannon

						QC 5 - 68	
						QC 5 - 9	
						QC 5 - 50	
						QC 5 - 30	
130 Powdercoat - 4 Black Sand - B4B	1 pcs	3/4/19	0.00 0.40	Powdercoat - 1 - B4B			
				Powdercoat - 2 - B4B			
				Powdercoat - 3 - B4B			BK 19-03-14
				Powdercoat - 4 - B4B			
135 QC 3	1 pcs	3/4/19	0.00 0.00	QC 3 - 10			
				QC 3 - 13			
				QC 3 - 15			HL 19-3-14
				QC 3 - 17			
				QC 3 - 18			
				QC 3 - 2			
				QC 3 - 26			
				QC 3 - 28			
				QC 3 - 3			
				QC 3 - 30			
				QC 3 - 34			
				QC 3 - 36			
				QC 3 - 38			
				QC 3 - 41			
				QC 3 - 51			
				QC 3 - 58			
				QC 3 - 59			
				QC 3 - 6			
				QC 3 - 68			
				QC 3 - 9			
140 Handfinish - 3-1- WingWalk-B4B	1 pcs	3/4/19	0.00 0.80	Handfinish - 3 - 1 - B4B			HL 19-3-14
				Handfinish - 3 - 2 - B4B			
				Handfinish - 3 - 3 - B4B			
				Handfinish - 3 - 4 - B4B			
				Handfinish - 3 - 5 - B4B			
150 QC 3	1 pcs	3/4/19	0.00 0.00	QC 3 - 10			
				QC 3 - 13			
				QC 3 - 15			
				QC 3 - 17			
				QC 3 - 18			
				QC 3 - 2			
				QC 3 - 26			
				QC 3 - 28			
				QC 3 - 3			
				QC 3 - 30			
				QC 3 - 34			
				QC 3 - 36			
				QC 3 - 38			
				QC 3 - 41			
				QC 3 - 51			
				QC 3 - 58			
				QC 3 - 59			
				QC 3 - 6			
				QC 3 - 68			
				QC 3 - 9			
160 Packaging 3-1 - Stock - B4B	1 pcs	3/4/19	0.00 0.00	Packaging 3 - 1 - B4B			
				Packaging 3 - 2 - B4B			
				Packaging 3 - 3 - B4B			
				Packaging 3 - 4 - B4B			
				Packaging 3 - 5 - B4B			
				Packaging 3 - 6 - B4B			

DAS
15
9-89

				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	DAS
				Packaging 3 - 34 - B4B	21
				Packaging 3 - 35 - B4B	9-86
				Packaging 3 - 36 - B4B	MAR 14 2019
170 QC 21 - SA	1 pcs	3/4/19	0.00 0.00	QC 21 - SA - 21	
				QC 21 - SA - 70	DAS
				QC 21 - SA - 53	21
					9-86 MAR 14 2019
Part Op 100 - (Weld per dwg A/R S.S. rod Batch: _____ - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld Descriptions: hinge (3) and Mounting brackets as per dwg D3914 ***Visual inspect before welding mesh*** 3- tack weld mesh on basket as per dwg D3914 ***Cut out mesh where label plate goes in center off basket lid as per dwg D4020-5. Make sure to place mesh correctly on lid, check with label plate before tacking mesh*** 110 - QC9- Inspect visual per QSI004- Fusion Welds 120 - QC5- Inspect part completeness to step on W/O 130 - Black Sandtex(Ref:4.3.5.7) per QSI005 4.3 *** mask sides of hinge prior to powdercoat*** 135 - QC3- Inspect Part Finish 140 - Wing Walk as per dwg QSI005 4.4 Batch <u>5146504</u> - Mask data plate and apply wing walk on outside surface of mesh as per dwg 2- Install label as per dwg ***Mask label plate to size of label, use scotchbrite red pad to lightly sand area for label, apply label *** 150 - QC3- Inspect Part Finish 160 - Identify as per dwg & Stock Location: _____ 170 - QC21- Final Inspection - Work Order Release					

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 pcs (2 ea)	100-Large Fab - Basket - 1	5146653
D3914-1	Rib	2 pcs (2 ea)	100-Large Fab - Basket - 1	5156484
D3914-7	Rib	2 pcs (2 ea)	100-Large Fab - Basket - 1	5156064
D4016-3	Hinge Half, Lid	3 pcs (3 ea)	100-Large Fab - Basket - 1	5110937
D4018-5	Rib	9 pcs (9 ea)	100-Large Fab - Basket - 1	5156244
D4020-5	Mesh (350 Basket Long, Lid)	1 pcs (1 ea)	100-Large Fab - Basket - 1	5153498
D4021-3	Data Plate	1 pcs (1 ea)	100-Large Fab - Basket - 1	5154112
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 pcs (2 ea)	100-Large Fab - Basket - 1	5157972

No master Unit.

Job Allocations				
Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D2581	2	75	0
	D3914-1	2	6	0
	D3914-7	2	8	0
	D4016-3	3	150	0
	D4018-5	9	63	0
	D4020-5	1	2	0
	D4021-3	1	4	0
	D4035-043	2	8	0
Part Specifications				
Specifications could not be found.				

Plex 2/5/19 9:48 AM Dart.Hadley.Shannon



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3914-041
Job Sheet 188197



Part No: D3914-041

Job Qty: 1 ea

Part Name: Long Basket Lid Assembly (350)



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 1/4/19

Job Tracking No:

Due Date: 3/4/19

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: DWG D4020 REV A SHEET 2, D3914 REV D SHEETS 1,2,3 IPP Rev:A new issue DD 10.03.19 verified by:EC
IPP Rev:B as per dwg revB DD 10.08.18 verified by:EC IPP Rev:C 13.03.14 AS PER DWG REV.pc1 DD
VERF:JLM IPP REV:D 13.06.21 DWG REV.C DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea		3/4/19	0.00	0.00	Start Up Large Fab-5		
100	Large Fab	1 pcs		3/4/19	0.00	6.67	Large Fab 1		
110	QC	1 pcs		3/4/19	0.00	0.00	QC9		
120	QC	1 pcs		3/4/19	0.00	0.00	QC5		
130	Powdercoat	1 pcs		3/4/19	0.00	0.40	Powdercoat4		
135	QC	1 pcs		3/4/19	0.00	0.00	QC3		
140	HandFinish	1 pcs		3/4/19	0.00	0.80	HandFinish3		
150	QC	1 pcs		3/4/19	0.00	0.00	QC3		
160	Packaging	1 pcs		3/4/19	0.00	0.00	Packaging3-2		
170	QC21-SA	1 Ea		3/4/19	0.00	0.00	QC21		

Part Op 100 - 1- assemble ribs , weld as per dwg D3914 using DT9607A 2- weld hinge (3) and Mounting brackets as per dwg
Descriptions: D3914 ***Visual inspect before welding mesh*** 3- tack weld mesh on basket as per dwg D3914 ***Cut out mesh where
label plate goes in center off basket lid as per dwg D4020-5. Make sure to place mesh correctly on lid, check with label
plate before tacking mesh***

130 - *** mask sides of hinge prior to powdercoat***

140 - 1- Mask data plate and apply wing walk on outside surface of mesh as per dwg 2- Install label as per dwg ***Mask
label plate to size of label, use scotchbrite red pad to lightly sand area for label, apply label ***

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 pcs (2 ea)	90-Start up Operation	
D3914-1	Rib	2 pcs (2 ea)	90-Start up Operation	
D3914-7	Rib	2 pcs (2 ea)	90-Start up Operation	
D4016-3	Hinge Half, Lid	3 pcs (3 ea)	90-Start up Operation	
D4018-5	Rib	9 pcs (9 ea)	90-Start up Operation	
D4020-5	Mesh (350 Basket Long, Lid)	1 pcs (1 ea)	90-Start up Operation	
D4021-3	Data Plate	1 pcs (1 ea)	90-Start up Operation	
D4035-043	Lid Rib Assembly, Aft (350 Basket)	2 pcs (2 ea)	90-Start up Operation	

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
-----------	----------------	----------	-----------	-----------

90-Start up Operation

D2581	2	15	0
D3914-1	2	6	0
D3914-7	2	6	0
D4016-3	3	185	0
D4018-5	9	18	0
D4020-5	1	6	0
D4021-3	1	12	0
D4035-043	2	4	0

Part Specifications

Specifications could not be found.



DART Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 813 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S162321



Part: D3914-041

Job No: 188197

Serial No/Batch: S162321

Revision: A/D

Inspector:

Exp Date:

Instructions: Various STC's

Date: 03/13/19